#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

69.28 File #:

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-011516 Address: 333 Burma Road **Date Inspected:** 10-Jan-2010

City: Oakland, CA 94607

**OSM Arrival Time:** 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes Zhu zhong hai. No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG** Components

## **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, S.Chandrakumar was present during the times noted above for observations relative to the work being performed.

## **OUTSIDE SHOP**

FCAW welding of weld joint 2F-056 located on PCMK SSD13-PP83 of 9EW welder is identified as 204730. ZPMC QC is identified as Mr.Li ping. The welding variables recorded by QC appeared to Comply with the WPS-B-T-2132-3.

SMAW welding of weld joint 4G-243 located on PCMK SSD10-PP80 of 9DW welder is identified as 207465. ZPMC QC is identified as Mr. Li ping. The welding variables recorded by QC appeared to Comply with the WPS-B-P-2214-TC-U4b-FCM-1.


SMAW welding of weld joint 4F-179 located on PCMK SSD11A-PP81 of 9EW welder is identified as 045246. ZPMC QC is identified as Mr.Li ping. The welding variables recorded by QC appeared to Comply with the WPS-B-P-2114-FCM-1.

During ZPMC MT on Deck panel diaphragm welds of segment 7DW they found 2 linear transverse indications. ZPMC QC Mr. Wang xian pin told that ZPMC will get Critical welding report (CWR) for that repair work, the weld no is identified as SSD12-PP58-004.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



## **Summary of Conversations:**

No relevant Conversation.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang-15--0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Chadra	Quality Assurance Inspector
Reviewed By:	Patterson,Rodney	QA Reviewer